

From: [Moore, Gary](#)
To: (b) (6)
Subject: F.J. Doyle Salvage (905 N. Poplar) Cleanup
Date: Friday, September 21, 2018 7:07:51 PM
Attachments: [Figure 5-1 Sample Grid Results Map - Excavation Depths.pdf](#)
[Figure 5-1 Sample Grid Results Map - Total PCBs Breakout.pdf](#)
[FJDoyle_20180919_Table 1.pdf](#)

Hello (b) (6)

Attached you will find maps and analytical data for the sampling that we did in May 2018. Your property was determined not to need a cleanup although the drainage ditch along Cottonwood in front of your house will. Additionally, we did have a detection for PCBs in the drainage ditch along Cedar but the level that was detected does not require cleanup. For your benefit, our cleanup level is 1 mg/kg Total PCBs. The maps being provide will show you the extent of contamination resulting from the historic operations at the former F.J. Doyle Salvage facility as well as the areas/depth of proposed actions.

1. Map showing all PCB detections throughout the evaluation area;
2. Map showing the areas to be excavated and the proposed depths of excavation;
3. Table with all sample results from the EPA investigation;

We anticipate starting the cleanup by the end of October or beginning of November.

Thank you and if you need anything, please do not hesitate to contact me

Gary W. Moore (6SF-ER)
Federal On-Scene Coordinator
U.S EPA Region 6
1445 Ross Ave, Suite 1200
Dallas, TX 75202-2733
Cell: 214.789.1627
moore.gary@epa.gov